
Section 1. Introduction

This guide will step through an example of welding a 3 pass overlay weld on a single part (in the example, a simple rectangular plate)

Setup Weld Project Video (Click to Play)

Section 2. PreSetup

See help for the "PreSetup" window.
Click "View Window" button below, then press <F1> key for help.

The usual case for this window is that we just accept the default settings.

Section 3. Load STL files

See help for the "StlFiles" window.
Click "View Window" button below, then press <F1> key for help.

For our example, open Setup -> Stl files or click "View Window" button below

- 1) - Click the "Copy stl files from" button and in the popup widget navigate to the directory where the stl files are stored and click OK.
 - in our test, this brings a file called PlateOnPlate.stl into the list of stl files.
- 2) - If you have more than one part in any stl files you need to split these into separate stl files. Either select the file in the list and click the "Split stl file" button or click the "Split all stl files" button.
 - In our example this returns 2 stl files:
 - PlateOnPlate_subset0001.stl
 - PlateOnPlate_subset0002.stl
- 3) - Visualize all stlfiles by clicking "Visualize all stl files" button.

In the Visualizer, for our example, we see 2 rectangular plates. A small one on top of a larger one. We plan to weld on the smaller one and use the larger one simply as a fixture.
- 4) - Scale to meters - All stlfile MUST be in meters for the software to behave properly.
 - Press the first mouse button in the Visualizer window and keep holding the button. Move the mouse a bit. Along the bottom of the Visualizer you should see the min max dimensions of the stls in meters. From this, you can determine if you need to scale and by how much.

- In our example, we see 200 x 36 x 400. Clearly we are not going to weld something that is 400 meters. We know that we really have parts that are 200 x 36 x 400 mm so we need to scale mm to meters. Just click the "mm to meters" button or type the scale factor into the slot next to the Scale button if it is not one of the 3 given conversions.

- You can repeat the visualizer check again to see if the dimensions reported along the bottom of the visualizer window are correct now.

we see 0.2 x 0.036 x 0.4 now

- Close the visualizer and the Stlfiles window

Section 4. Setup part type info

See help for the "PartTypeInfo" window.
Click "View Window" button below, then press <F1> key for help.

Open the Setup -> Part type info window or click "View Window" button below

- you need to assign stlfiles to part types. You do this by selecting the Part type in the list on the left and entering a substring from the stlfile name in the upper right SubString widget which distinguishes the desired file or files. Then click the "Update stl files" button. You can enter several substrings or sometimes it is even appropriate to enter * and bring every stlfile in.

- in our example, we select "Body" and enter substring "0001"
The file PlateOnPlate_subset0001.stl appears in the list on the right.
- we select "Constraint" and enter substring "0002"
The file PlateOnPlate_subset0002.stl appears in the list on the right.

The other Part types are left blank in this example.

--You can also change the Material for each Part type by selecting the part type and the selecting from the menu in the lower left. Press Apply for each part type.

For our example we set to PriceLowAlloySteel

Section 5. PreProcess

See help for the "PreProcess" window.
Click "View Window" button below, then press <F1> key for help.

Note: for the single part case the "Make STL adjacency graph" button need not be pressed. If you do, it will give an Error. Ignore it.

Section 6. Assign part adjacency

See help for the "Part Adjacency" window.
Click "View Window" button below, then press <F1> key for help.

Note: for the single part case this step is not needed. If you do, it will give an Error. Ignore it and continue.

Section 7. Pick weld paths

Since this guide is mainly concerned with welding on a single part we will only discuss the PointCurve method. You can read about other weldpath picking methods in other guides such as the regular "Prepare welding Project" guide.

-
1. Open Setup -> Stl Files (or click "View Window" below).
 2. Click "Visualize all stl files" in the "Stl Files" window. This pops up with all stl files.
 3. Open Tools -> "WeldPath - PointCurve" window in SMTVisualizer to pick weld paths. then press <F1> key for help.

For our example, we just pick 2 points right down the center of the smaller plate and save in a file called wp1

Section 8. Mesh weld paths

Since this guide is mainly concerned with welding on a single part we will only discuss the PointCurve method. You can read about other weldpath picking methods in other guides such as the regular "Prepare welding Project" guide.

1. Open the Meshing -> Predefine -> WeldPath -> Edit window from the main menu (or click "View Window" button below).

2. Set the WeldPath Type to: PointCurve.

3. Select the filename of the weldpath points saved in the previous step

Set up the rest of the meshing parameters (see F1 help for this window) and save parameters with "OK" button.

3. Click "Meshing -> PreDefined -> WeldPath -> Make".

4. Click "Meshing -> PreDefined -> WeldPath -> Visualize".

You may need to rotate to see the path if it is in the Z direction

for our example,

WeldPath Type: PointCurve

WeldPath name: wp1

maxElemSize 0.005

all other parameters, accept the defaults.

Section 9. Weld Path Group

1. Open the Meshing -> Predefine -> WeldPath -> Edit window from the main menu (or click "View Window" button below).

2. WeldPathGroup -> Make

3. WeldPathGroup -> Visualize

Section 10. Create weld procedures

See help for the "Weld Procedure" window.

Click "View Window" button below, then press <F1> key for help.

Create Weld Procedure Video (Click to Play)

For our example,

1) - Click New and enter a name for a weldprocedure in the popup widget
For example, type a and click ok

This creates a new weld procedure with default settings.

For our example we alter the values to be:

Weld Speed: 0.006 m/s
Wire diameter: 0.0016 m
Voltage: 29.0
Current: 270.0
Arc Efficiency: 0.85

Front: 0.008
Rear: 0.016
Width: 0.0085
depth: 0.008

Click Apply and then OK

Section 11. Create weld joints

At this point you only need to do one step in the "WeldJoint" window.

1. Click "LoadWeldPaths" button.

This creates the list of weld joints with default parameters for the filename which was selected for making weld paths.

Also see help for the "WeldJoint" window.

Click "View Window" button below, then press <F1> key for help.

Section 12. Mesh weld joints

Since this is for a special case (One part, multipass) we will discuss only the relevant case here. Other guides discuss other possibilities

Expand this entry and follow the steps....

Section 12.1. Mesh weld joints: Make Big WeldJointByTube

Meshing -> Predfined -> WeldJointByTube1 or click "View Window" button below

The method we will use here, first makes a WeldJointByTube which is larger than the desired final weld profile. That is, make a large Tube, large enough to encompass all the weld passes geometry to will need. The later steps will make the actual passes profile geometry that will be solved.

- 1) - In the WeldJoint window select the desired weldpath
In our example, there is only one.
- 2) - In the WeldJointByTube1 window, click the "Set current weld joint"
note that the weldpath number appears next to weldPathIds:
- 3) - Choose a radius large enough to encompass all the weld passes
- for our example, 0.03
- 4) - cornerSize - because this is on a flat surface of only one part set this to 0.0
- 5) - fakeSize: Since only one part need only one number,
in the example, set this to 0.03
- 6) - change the nbElementsOnArc to at least 5 to make a good half circle
- 7) - fakeLayers: in example, set to 2
- 8) - shift: in example, set to 0.0
- 9) - nbElementsThroughThickness: in example, set to 3
- 10) - thickness: in example, set to thickness of the plate 0.012
Hint: If you don't know it, You can determine this using the visualizer Tools -> Slider
- 11) - click Apply and OK

Leave "Pattern Mesh 2D" set to none for now.

- 12) - Meshing -> Predfined -> WeldJointByTube1 -> Make
- 13) - Meshing -> Predfined -> WeldJointByTube1 -> Visualize

Close Visualizer.

Section 12.2. Mesh weld joints: Make crossSection Linemesh

Mesh Weld Joints Video (Click to Play)

After we have our Big Tube from the previous step we want to use the Electrode points picker to make our multi-pass profile geometries.

Because this is only one part, our usual methods for getting a crossSection, such as using the WeldGroup weldjoint maker do not work right now. We will instead make ourselves a LineMesh using a special mesher found in the Meshing -> UserMade window.

* - To start, open the Setup -> StlFiles window and visualize the part you need the cross section of. In our example, choose PlateOnPlate_subset0001.stl

* - Open the visualizer's Tools -> Multi Point Picker and choose a set of points on your

part which will form a loop of the cross-section

- In our example, since it is a simple rectangle, we will pick 4 points around the end facing us when the visualizer pops up, picking in a counterClockwise direction. Save the points in a file called, for example, ptLine

Close the visualizer and the Stlfiles window.

Open Meshing -> UserMade window or click "View Window" button below

1) - Click the New button and in the popup select MeshType: PointLine and enter a name for the mesh, for example, linemesh and click OK

2) - Select the name you just created (linemesh) and Click Edit

3) - In the popup next to "Multi Point Picker" select the ptLine filename which you made earlier.

4) - Next to "pointlineMeshPNum" enter the part number of the part you made the linemesh cross-section of. (You can see this by looking in the Setup->PartTypeInfo window next to the part stlfile name) In our example, 1201

5) - Next to "pointlineMeshLoopFlag" enter 1 (This causes the linemesh to close by connecting the first and last points)

6) - Click Apply and OK

7) - Meshing -> UserMade -> Make

8) - Meshing -> UserMade -> Visualize

Keep the Visualise window open and proceed to the next item in the guide

Section 12.3. Mesh weld joints: Select Electrode Points

In the previous item in this guide we made a linemesh which was a cross-section of the part we want to make filler metal on. If it is not already, Visualize it.

This page describes the process of picking Electrode Points to make FillerMetal

* - In the Visualizer, popup Tools -> ElectrodePoints
You probably also need the Tools -> PointPicker-Slider

* - pick 2 points on the linemesh which will be the ends of your fillerMetal profile. In our example, we want to make a filler metal profile that is 14mm wide in the center of the top line. We do this by using the PointPicker-Slider

- Select the left top corner of the rectangle with the first mouse button and click Set in the PointPicker-Slider next to "Start Point"

- Select the right top corner of the rectangle with the first mouse button and click Set in the PointPicker-Slider next to "End Point"

- Using the slider in the PointPicker-Slider move to the left 7mm and click Pick button

on PointPicker-Slider (You can see the distance it moves on the slider)

- after clicking Pick on the PointPicker-Slider go to the SetElectrodePoints window. If "Electrode ID" shows 0, click the "New Electrode" button. Then click the Set button next to the "Start Node"

- repeat the process for the right point. Move the PointPicker-Slider 7mm past the midpoint to the right and click Pick Then click Set next to the "End Node" in the SetElectrodePoints window.

* - Write the electrode points into a file with a name that you will recognise again. For our example, we will use ep1

You can pick multiple sets of Electrode Points at this time if desired but since we want to actually pick points on the profile of the first weldMaterial to make the 2nd and 3rd profiles, we will now proceed to the next item in the guide, FillerMetalMaker which actually makes the profile you can see.

Section 12.4. Mesh weld joints: FillerMetalMaker

Open the Meshing -> Predefined -> FillerMetalMaker -> Edit or click the "View Window" button below

1)- Open the WeldJoint window and select the weldpath in question.

2) - In the FillerMetalMaker Edit window click the "Set current weldjoint" button

3) - Click the Set button next to the "Parts linemesh CDF file" and in the popup select the file which contains the linemesh file you made in a previous step. The file will be the filename you wrote but with Mesh2 prepended. In our example, we select Mesh2linemesh.cdf

4) - Next to the "Electrode Points" select the filename you saved your electrode points in in the previous step. For our example, ep1

5) - Some default numbers for parameters show up in the slots of the FillerMetalMaker -> Edit window.

For our example, we increase the number next to area: 4e-05
change nbElements: 100
change dx: 0.00002

MUST turn on "fillerMetalPointsFlag" 1 (This is because of the way we picked electrode points on the surface rather than as a vector)

The other defaults should be ok

6) - Click Apply and OK

7) - Click Meshing -> Predefined -> FillerMetalMaker -> Make

8) - Click Meshing -> Predefined -> FillerMetalMaker -> Visualize

This is now sufficient to continue for one pass. If you want to make multipass at this time, go back to the "SelectElectrodePoints" item in this guide, using this new Visualizer to pick your points. Open the Tools->ElectrodePoints and start by loading the file you did

before and click "New Electode". You can now pick points on the profile line of previous weld materials.

Repeat as necessary to build up your multipass profile set.

Section 12.5. Mesh weld joints: Make PlaneSurface mesh

Next we will make a surface mesh using the outline of the parts cross-section and weldMaterial profile(s) made in previous steps

Open the Meshing -> User made window or click on the "View Window" button below.

- 1) - Click the New button and in the popup Select MeshType "PlaneSurface"
enter a name that you will recognise again, for our example we just called it planeSurface Click OK
- 2) - Select the name you just made in the list in UserMade (planeSurface) and then click the Edit button.

Next to the "Line mesh CDF file" click the Set button and in the popup select the file made by the previous step "MeshFillerMetalMaker-0.cdf"

Edit the other parameters as follows:

```
dx: 0.001
compatibleFlag: 1
meshQuads: 1
makeBRepFlag: 1
```

- 3) - Click Apply and OK
- 4) - Click Meshing -> User made -> Make
- 5) - Click Meshing -> User made -> Visualize

Note: The mesh shown may have sharp corners clipped by the meshing process used
The matching BRep file should be better. (It is written if makeBRepFlag set)

Section 12.6. Mesh weld joints: SurfaceReMesher

We will now use the BRep file from the previous step to make a better mesh of the 2D cross-section mesh we made in the previous step

Click on the Meshing -> UserMade window or click the "View Window" button below

- 1) - Click the New button and in the popup Select MeshType "SurfaceReMesher"
enter a name that you will recognise again, for our example we just called it surfReMesh Click OK
- 2) - Select the name you just made in the list in UserMade (surfReMesh) and then click the

Edit button.

Click the Set button next to the "Tri mesh CDF file" and in the popup, navigate up one level to the brep directory and select the file brep_electrodeFM_0.cdf

edit other parameters as follows:

```
minElemSize: 0.001
maxElemSize" 0.002
```

- 3) - Click Apply and OK
- 4) - Click Meshing -> User made -> Make
- 5) - Click Meshing -> User made -> Visualize

Check the mesh in the Visualizer by selecting View->Mesh

Section 12.7. Mesh weld joints: Make WeldJointByTube1

Now, at last, we are ready to make the actual weldJoint that we will use for the analysis.

Open the WeldJoint window and select the weldpath in question

Open the Meshing -> Predefined -> WeldJointByTube1 window or click the "View Window" button below

- 1) - Click the "Set current weldjoint" button
- 2) - The window should still have the settings for the Big Tube that we made as the first item under "Mesh weldjoints" in this guide
We will now open the menu next to "Pattern Mesh 2D" and select the mesh we just made in the previous step. In our example, surfReMesh
- 3) - Click Apply and OK
- 4) - Click Meshing -> Predefined -> Make
- 5) - Click Meshing -> Predefined -> Visualize

Check the mesh in the Visualizer by selecting View->Mesh

Section 13. Setup weldjoint parameters

Setup Weld Joint Parameters Video (Click to Play)

This step can only be done after the weld joints are meshed.

Open the "WeldJoint" window or click "View Window" below.

As a test, you can click "ComputeWeldingTimes" button before setting any weld joint parameters. This must work with the default parameters set by "LoadWeldPaths" button. If it doesn't work there is some inconsistency between the weld paths, weld joint meshes and filler metals. This has to be resolved before you go further.

Setup parameters for all weld joints, passes and sub-passes (steps 1-6).
When you finished setting parameters for one weld joint (pass) click "Apply" button at the bottom before you choose another weld joint, otherwise all the new parameters will be lost.

1. Set passes using "SetPasses" button for each weld joint which has more than one pass.
2. Choose weld procedures for each weld pass. By default, the first weld procedure from the weld procedure list is chosen.
3. Set sub-passes for each weld joint (pass) if needed.
4. Set delay times for all weld joints, passes and sub-passes.
5. Set weld pool centers if needed.
6. Setup tack welds sizes and types for each weld pass.
7. Click "ComputeWeldingTimes" button. This computes the welding times of each sub-pass of each weld pass using the length of the sub-pass and the weld speed defined in the weld procedure.
8. Choose the Analysis type. Based on the selected type, the start times are computed using welding times and delay times.

EXAMPLE

For our PlateOnPlate example, we want to start and end our welding 25mm from the edge of our 200mm long part so we edit as follows:

```
startWF: 0.125
endWF:   0.875
```

- * - Don't forget to Apply after editing for any particular weldpath.
- * - Click the ComputeWeldingTimes button
- * - Next to the "Tack Weld Type:" select None (we are welding on a single part here so we don't need tack welds) Don't forget to Apply the change.
- * - when we are satisfied with the parameters click OK

Section 14. Mesh Parts

See help for the "Setup->Part Attributes" window.
Click "View Window" button below, then press <F1> key for help.

For jobs which use "real" weldJoints, the parts are meshed using the preMesh Flag on.
Otherwise, this flag should be off.

For our PlateOnPlate example we will do a 2 step process.

We will mesh the Plate using the MesherType: PQSurface with the preMesh flag off
Then we will cut out the elements around our weldJoint (our preMesh) and then mesh again
using the MesherType: GeneralSheetMetal to mesh the elements that are between the weldJoint
(premesh)and the rest of the PQMesh

To start, we know that the PQSurface mesher needs a file with 4 points on the top surface
(patch 0) which we will pick in a counter clockwise order.

* - select the part stlfile name in the lefthand list

* - click BRep-View Parent

* - In the visualizer that popped up, Rotate so you are looking at patch 0 (Red)

- In the Visibility->Part turn off all except patch 0

- In the Visibility->Mesh turn off all except patch 0

- Turn on View->Mesh

- Open Tools->MultiPointPicker and pick 4 point (In our example, pick the 4 corners of
the rectangle) For each point, pick with the left mouse button, click "New Point" in
MultiPointPicker and Set button next to "Point"

- write a file to save these pq points, say file pq4pts_ss1

- close visualizer

* - Select MeshType: PQSurface and then Click Options button below

In the popup window, on the left side next to the "Outerloop points" button select the
pq4pts file you just wrote from the menu list

Edit other parameters as follows:

resolution: 0.005

pq: 20 40

preMeshFlag: 0

Other parameter defaults should be ok

Click Apply and OK

* - In the Part Attributes window click the Mesh-Make button and watch the log until it
says Done!

- when the mesher says Done click Mesh-View and check the mesh

- Click the Mesh-Save button (this is important if you want to keep the PQ portion of
your mesh. If you forget this button, you mesh will be completely done by
GeneralSheetMetal mesher. [Which is ok but PQ is nicer])

Now

* - Select MeshType: GeneralSheetMetal and then Click Options button below

Edit parameters as follows:

MaxElementLength: 0.01

MinElementLength: 0.002

nbElementsAlongThickness: 3

partMeshFlag: 1 (This says to cut out around the weldjoint (premesh)
from the PQ Mesh)

- Click Apply and OK

* - In the Part Attributes window click the Mesh-Make button and watch the log until it
says Done!

- when the mesher says Done click Mesh-View and check the mesh
- it will have a hole where the premesh will be

* - Click "MergeBody" button on the far right of the Part Attributes window
and when Done Close the window

Section 15. Make Total mesh

Make the total mesh by selecting MergeWithCMat in the Meshing window and clicking "Make" button (Meshing -> Predefined -> MergeWithCMat -> Make).

This merges the WeldGroup and Body meshes together. It also makes a special matrix to provide connectivity between WeldGroup and Body as they are not compatible in general.

The total mesh can also be viewed using Meshing -> Predefined -> Total -> Visualize.

Section 16. Create subdomains

See help for the Meshing -> predefined -> "ReorderElementsSD mesh parameters" window. Click "View Window" button below, then press <F1> key for help.

For our example, edit as follows:

Number of layers to grow from weld joint: 10
Number of elements in weld joint subdomain: 1000

- * - Click Apply and OK
- * - click Meshing -> predefined -> ReorderElementsSD -> Make
- * - click Meshing -> predefined -> ReorderElementsSD -> Visualize

Section 17. Define constraints

There are two types of constraints:

1. Node fixities;
2. Stl fixities.

Section 17.1. Define constraints: Node fixities

Node fixities are the nodes which are restrained to move in certain directions.

1. Visualize "Total" mesh (Meshing -> Predefined -> Total -> Visualize) and continue with SmtVisualizer GUI.
2. Tools -> Set Node Fixities.
Read help for the "Set Node Fixities" window.

For our example, we want to make nodal fixities such that our plate has the rigid body modes constrained. We will pick 3 nodes in Y (front 2 corners and center at far end), 2 nodes in Z on either side in mid length of the plate and 1 node in X at the center of the Plate. All these nodes picked on the bottom of the plate.

Write to a file called, in our case, fix1

Note: If the mesh changes, say you mesh a different weldjoint, then you will need to repick these fixities

Section 17.2. Define constraints: stl fixities

Stl fixities are the stl files which make all adjacent nodes in the total mesh to be restrained to move in certain directions.

1. Visualize all stl files using "Setup -> Stl Files -> Visualize all stl files" or "Meshing -> Predefined -> ViewStl -> Visualize" and continue with SmtVisualizer GUI.
2. Tools -> Set Stl Fixities.
Read help for the "Set Stl Fixities" window.

Section 18. Setup Boundary Conditions

Setup Boundary Conditions Video (Click to Play)

Setup Boundary Conditions

Section 18.1. Setup Boundary Conditions: Thermal

See help for the Setup->"Boundary Conditions" -> Thermal window.
Click "View Window" button below, then press <F1> key for help.

Section 18.2. Setup Boundary Conditions: Stress

See help for the Setup->"Boundary Conditions" -> Stress window.
Click "View Window" button below, then press <F1> key for help.

This is where you will set the start and end times for the various Constraints files (such as fixities) and Forces which you have created earlier.

Section 19. Setup process parameters

Various parameters must be setup to define the specific analysis that is to be run. What are the loading conditions, solvers parameters, etc

Expand this guide entry to access more detailed help for each type available.

Section 19.1. Setup process parameters: Thermal parameters

See help for the "Thermal Process Parameters" window.
Click "View Window" button below, then press <F1> key for help.

For our example we edit the parameters as follows:

Analysis end time: 10000.0
Power Density button: ON

Apply and OK

Section 19.2. Setup process parameters: MicroStructure parameters

There is no special MicroStructure parameters right now.

Section 19.3. Setup process parameters: Stress parameters

See help for the "Stress Process Parameters" window.
Click "View Window" button below, then press <F1> key for help.

For our example, set "MicroStructure Data Flow From" to "this"

Write Time Step Stride: 10

Other default parameters are ok

Section 20. Run Analysis

See help for the "Run Analysis" window.
Click "View Window" button below, then press <F1> key for help.

Section 21. View Results

Multipass Preheat Delay Video (Click to Play)

The above video Multipass Preheat Delay shows how to setup a multi-pass analysis when each weld pass is delayed until the interpass temperature reaches a certain level. In this case, the specified interpass temperature level was 50 C or 323 K.

There are several ways to look at results of analyses from looking at colors on geometry to animations to making plots and comparing projects.

Each are dealt with briefly in the items under this heading.

Section 21.1. View Results: Plot

VrWeld can also produce several kinds of line plots from PointData vs Time to MinMax values over time to ETA Estimates for how long a job is expected to take which can be run during analysis.

More help is available using F1 on the popup windows for these menu items

To use MinMax for Temperature for example, open Plot->MinMax or click "View Window" button below

Pick the Field name you want from the menus and click Run, then View Plot

You could also click ViewData button which gives it in table form

For our example, we want to start the second weldpass when the first pass cools to a temperature of 50C or 323K. The time when the max time cools to 323K can easily be read off the table.

You could then go back to the weldJoint window, select Analysis type Manual, select the pass in question and set the Start Time to the value you need. Then rerun the job either from the beginning or from the nearest Restart file.

In Stress Process Parameters we could for example, run the first weldpass with the later passes set with start time way far in the future beyond the scope of the job so they won't

start for the first run. Set the Restart "Write Time Step Stride" to say 10 This mean we have a restart file for every 10th timestep. We then do not need to rerun the entire job, just pick up from the last restart file and solve for the second pass. repeat for the 3rd pass

In our example, We want to plot the NodalStress along a line from left to right across the center of the length of the plate. We want this line to be 1.5mm inside the part. We do this by picking with the slider on each side of the plate and the clicking Set next to "Node Position 1" or Node Position 2"

Set Number of points desired and set the last time step number in the "Time Step List" and turn off the stride function by setting "Global Time Step Stride" -1